



GARY R. HERBERT  
Governor  
SPENCER J. COX  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

## Minerals Inspection Report

Report Date: 07/15/2014

Reviewed

*PRG*

Mine Name: Pine Canyon Mine	Permit Number: M/045/0004	Mine Status: Active
Operator Name: Rio Tinto - Kennecott Utah Copper	Inspection Date: August 21, 2013	Permit Fees: Paid
Inspector(s): L Heppler, A Abate, T Nicolaysen	Inspection Time: 3:00 PM	Bond Amount: \$134,905
Attendee(s): T Lindsay, T Heaton	Weather: Sunny, Dry	Bond Escalation: 12/01/2016
Inspection Purpose: Routine annual inspection		Prior Inspection: May 10, 2012

### Conclusions and Recommendations

OGM to continue annual inspections and monitor the site when in the area.

Elements of Inspection		Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds Permit fee and reclamation bond is up to date,	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2.	Public Safety (shafts, adits, trash, signs, highwalls) Mine site is accessed through a paved road and locked gate. No trash was noted on site. Both portal and shaft were secure.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3.	Protection of Drainages/Erosion Control No erosional problems were noted during inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.	Deleterious Material No deleterious material was stored on site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5.	Roads (maintenance, surfacing, dust control, safety) Roads were well maintained.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6.	Reclamation No concurrent reclamation at the site.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts) No regrading at this site	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8.	Soils No soil stockpiles are noted at the time of inspection.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9.	Revegetation Area revegetation is a successful, dominantly grasses but also includes biodiversity and locally established conifers.	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10.	Other This line is intentionally left blank	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

CC: Chris Kaiser - Kennecott

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M045-Tooele/M0450004-PineCanyonMine/inspections/INSP-08212013.pdf





Portal



Shaft structure - looking east



Top of shaft structure - looking west



Old tram on skyline